

HASTINGS (9D9) 3 W UTC-5(-4DT) N42°39.80' W85°20.75'

800 B TPA-1600(800) NOTAM FILE LAN

RWY 12-30: H5003X75 (ASPH) S-20 MIRL**RWY 12:** REIL. PAPI(P4R)—GA 4.0° TCH 34'. Thld dspcd 241'. Tree.**RWY 30:** REIL. PAPI(P4L)—GA 3.0° TCH 43'. Thld dspcd 251'. Tree.**RWY 09-27:** 2380X170 (TURF)**RWY 09:** Thld dspcd 191'. Tree.**RWY 27:** Thld dspcd 374'. Tree.**RWY 18-36:** 1952X200 (TURF)**RWY 18:** Tree.**RWY 36:** Tree.**SERVICE:** S4 FUEL 100LL, JET A+ LGT ACTIVATE MIRL Rwy 12-30, PAPI Rwy 12 and Rwy 30, REIL Rwy 12 and Rwy 30—CTAF. Rwy 30 PAPI unusbl byd 5° left of cntrln.**AIRPORT REMARKS:** Attended irregularly. Lrg flocks of lrg birds on and invof arpt. Rwy 09-27 and Rwy 18-36 mkd with 3' yellow cones.**AIRPORT MANAGER:** 269-945-6306**COMMUNICATIONS:** CTAF/UNICOM 123.075

Ⓡ GREAT LAKES APP/DEP CON 128.4 (1030-0500Z±)

Ⓡ CHICAGO CENTER APP/DEP CON 128.4 (0500-1030Z±)

CLEARANCE DELIVERY PHONE: For CD ctc Great Lakes Apch at 269-459-3344, when Apch clsd ctc Chicago ARTCC at 630-906-8921.**RADIO AIDS TO NAVIGATION:** NOTAM FILE GRR.**VICTORY (H) (H) VORW/DME** 115.95 VIO Chan 106(Y) N42°47.20' W85°29.82' 142° 10.0 NM to fld. 802/4W.
DME unmonitored.


DME unusable:

011°-314° byd 30 NM blo 3,000'

CHICAGO

H-5E, 10F, L-281

IAP

**HAT FLD** (See NUNICA on page 228)**HELSEL****ALBERT J LINDBERG** (5Y1) 2 N UTC-5(-4DT) N46°02.13' W84°25.06'

760 B NOTAM FILE GRB

RWY 09-27: H3700X60 (ASPH) S-30, D-60 MIRL**RWY 09:** PAPI(P2L)—GA 4.0° TCH 40'. Thld dspcd 187'. Road.**RWY 27:** PAPI(P2L)—GA 3.5° TCH 25'. Trees.**SERVICE:** FUEL 100LL LGT Actvt PAPI Rwy 09 and 27; MIRL Rwy 09-27—CTAF.**AIRPORT REMARKS:** Unattended. 100LL: For AvGas call 989-513-2207. For FICONS call AMGR or 989-513-2207. Rwy 09 and Rwy 27 markings are faded.**AIRPORT MANAGER:** 906-430-8034**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Minneapolis ARTCC at 651-463-5588.**RADIO AIDS TO NAVIGATION:** NOTAM FILE PLN.**PELLSTON (L) (L) VORTACW** 111.8 PLN Chan 55 N45°37.84' W84°39.85' 029° 26.4 NM to fld. 836/6W.


VOR unusable:

301°-339°

GCP has azm only, no DME at GCP

LAKE HURON

L-31B

**HIGHLAND****PONDEROSA HELIPORT** (13D) 2 W UTC-5(-4DT) N42°37.75' W83°40.99'

1017 NOTAM FILE LAN

HELIPAD H1: H18X18 (CONC) RWY LGTS(NSTD)**SERVICE:** LGT ACTIVATE nstd perimeter lgts helipad H1, VASI helipad H1—CTAF. H1 nstd perimeter lgts due to amber color. Helipad H1 one box VASI located on west side of pad 10° south 270°. Recommend heading 260° for approach to use VASI.**HELIPORT REMARKS:** Unattended. Deer and birds invof heli. Tree haz in all drctns.**AIRPORT MANAGER:** 248-887-3821**COMMUNICATIONS:** CTAF 123.025**CLEARANCE DELIVERY PHONE:** For CD ctc Detroit Apch at 734-955-1404.

DETROIT

COPTER